

System Entry 1/10/2025

Billing info

Brian Glassman 8000 E. Prentice Avenue, Suite B-6 URL Posted Date 1/10/2025

Greenwood Village, CO 80111

bryan@bondgc.com

(720) 598-5020

(720) 598-5020(matt)

Description	Price
*Single Gate #2 Firecourt: Gate style 72. R.O. between jambs 35" x 67-3/8" net ht. 2-1/4"T stiles and rails. 3/4"T x5 "T&G Solid floating panel	\$3,322.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
*Single Gate #4 Master Bath Terrace: Gate style 72. R.O. between jambs 43-1/2" x 69-1/8" net ht. 2-1/4"T stiles and rails. 3/4"T x5 "T&G Solid floating panel	\$3,322.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
*Single Gate #5 Dog Enclosure Fence: Gate style 5 modified. R.O. between jambs 42-1/2" x 59" net ht. 2-1/4"T stiles and rails. Upper pickets 1-5/8" x 1-5/8" diagonal (2-1/4" corner-to-corner). 3/4"T x 5 "T&G lower solid floating panel	\$3,672.00
*Pair of surface-mounted jambs 1-1/2"T x 5"W	\$225.00
*Single Gate Pool House Shower Enclosure: Gate style 40-7. R.O. between jambs 34" x 83-3/8" net ht. Upper/lower pickets at 1-5/8"T x 3 -1/2"W w/eq. spacing. 2-1/4"T stiles and rails Note: 1/10/25 Added \$225 for revised ht of 83-3/8".	\$4,300.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
*Double Gates #1 Entry Courtyard: Gates style #72. R.O. between jambs 67" x 73-1/4" net ht. 2-1/4"T stiles and rails. 3/4"T x5 "T&G Solid floating panel	\$6,644.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
*Double Gates #3 to Kitchen Garden: Gates style 5 modified. R.O. 46" x 67-3/8 net ht. 2-1/4"T stiles and rails. Upper pickets 1-5/8" x 1 -5/8" diagonal (2-1/4" corner-to-corner). 3/4"T x 3-1/8"W T&G lower solid floating panel	\$7,344.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
*Double Gates #6 at Pool: Gate style 72. R.O. between jambs 74-3/4" x 54-1/8" net ht. 2-1/4"T stiles and rails. 3/4"T x5 "T&G Solid floating panel	\$6,644.00
*Pair of embedded jambs 3"T x 5"W	\$475.00
<u>Double Gates at Caretaker's Vestibule:</u> Gate style 8 modified. R.O. between jambs 71-7/8"x 64"net ht from grade to springline. 180° inverted top rail @ 18" rise. Pickets 1-5/8"T x 3-1/2"W EQ spacing. Center stiles top profiles. 1-5/8"T stiles and rails. *(6/23/25: revised stile/rail from 1-5/8" to 2-1/4"T.	\$8,875.00
Distressed brushing to Entry Courtyard dbl gates, Fire Court gate, and Kitchen Garden dbl Gates.	\$2,350.00

System Entry 1/10/2025

Billing info Brian Glassman 8000 E. Prentice Avenue, Suite B-6 Greenwood Village, CO 80111

URL Posted Date 1/10/2025

bryan@bondqc.com

(720) 598-5020 (720) 598-5020(matt)

Adv Pay Date

Credit Card Number

Adv Pay Approve

Final Pay Date Final Pay Approve

Item Subtotal \$49,548.00

Delivery \$2,025.00

Grand Total \$51,573.00

Advance Pay Final Pay

Balance Due \$51,573.00

NOTES:

Payment: A 50% advance is processed (via card or check) prior to the start of all work. Final payment will be processed upon completion of your order and prior to shipping.

<u>Cancellations:</u> Because we are a custom, made-to-order shop, there is a fee of 25% of your advance payment not to exceed \$1,000 for cancellations prior to the approval of your drawings. **There are no refunds once the drawings have been approved.

<u>Pricing Quotes:</u> Quoted and agreed upon pricing remains valid for 1 month from when your payment information is entered. If after 1 month and the project has not arrived at the stage of creating drawings, or the drawings have not been approved, the original quote is subject to review.

Storage: Products are preferably shipped or delivered within 2 weeks of posting completed photos.

Hardware: There is a 25% fee for all returns of unblemished products within one month of sale. Items that have been installed and exposed to the weather are non refundable unless they are defective.

Standard Lock-sets and Electronic Access: The use of standard 2-3/8" back-set locks over traditional gate latches is not recommended. This includes certain electronic access specifications requiring minimal swing clearance. Normal expansion of your gate will occur and the clearance required for a standard 2-3/8" lock-set (1/4" max) puts the gate at risk of becoming wedged against the jamb, requiring the sort of effort with each passage that can damage the gate. We cannot support the integrity of any gate that uses a standard back-set lock-set. We insist upon the use of Gate Latches or dead bolts allowing 3/8"-1/2" clearance between the edge of the gate and the jamb or post.

<u>Finishing:</u> All products must be fully exposed to your regional climate for 3 weeks prior to applying any solid or opaque finishes. Our WoodRX absorbing finish is available as a pre-finish or can be applied upon receipt of products. WoodRX color charts vary on the finished product as per inherent hues and tints of western cedar.

Shipping/Crating: It is always best to have someone present to accept delivery. In the event of a potentially damaged crate, you must sign off on the delivery receipt at the time of delivery noting the possibly damaged crate. If on later inspection, there is damage to the product, you must contact UPS freight at the number on your receipt to report this damage within 5 days of delivery and request an inspector. If damage is not noted on the delivery receipt and UPS is not contacted within 5 days, liability falls on the receiver. Prowell Woodworks will not automatically replace your damaged product free of charge.

****Please review your statement and drawings for accuracy. Upon approval, please provide your signature and date, confirming the accuracy of both the statement and dated drawings.

****Drawings dated June 27, 2025.

Approval Signature	D	Date	
• •			