



Notes:

If the stone veneer is too irregular to mount the jambs directly to the stone, then the jambs need to be embedded such that they mount to the block core. In that scenario, *we need the measurement from the core block to the outermost stone* to establish the thickness of the jambs. They're shown (and priced) at 1-1/2" thickness and proud of the outermost stone 1/2". This would put your stone veneer at only 1" thick. Is that correct?