


Set #3.


One pair of identical gates (2 singles)



NOTES: Motor arm is at 18-1/2" from grade? Concrete motor footing is formed such that the motor arm mounts to the center of the 3rd rail from the bottom, at 21".(To be field verified)

Typ left gate viewed from property side

Dated Dec 29, 2025



* The height placement of the motor-arm mounting plate to be field verified.