


MOUNTING EMBEDDED STEEL FRAMES TO CPW COLUMNS

A typical view of mounting an embedded steel frame to the CPW Columns. The site contractor welds a plate off the steel post, which is in turn mortised to pass through the CPW column. The Gate arrives with an exposed weld plate at hinge points. This weld plate is welded to the inner, embedded steel frame. The hinge system itself, and it's required clearance, are provided by the contractor and called out in the resulting drawings



CHARLES
PROWELL
WOODWORKS